



## 1,000 GALLON GREASE INTERCEPTOR REVISED: 7/2/07 DRAWING NOT TO SCALE





## **NOTES:**

- CONCRETE TO BE 4000 PSI @ 28 DAYS
- BUTYL RUBBER SEALANT USED AT JOINTS
- 24" ACCESS HOLE SUITABLE FOR RING AND COVER